



NB: ELECTRIC HEATERS WILL INCREASE SURFACE TEMPERATURE AT LOW VELOCITIES. MIN 1.5 M/S

HIGH VELOCITY (ABOVE 6 M/S) MAY CAUSE THE REAR OF THE ELEMENT TO OVERHEAT, REDUCING SERVICE LIFE.